

CERTIFICATE OF COMPLIANCE

Certificate Number 20160707-E244889
Report Reference E244889-20110705
Issue Date 2016-JULY-07

Issued to: TELEGAERTNER KARL GAERTNER GMBH
LERCHENSTR 35
STEINENBRONN , 71144
Germany

**This is to certify that
representative samples of**

Communications-, Audio/Video-, Data- and Other Signaling-
circuit Accessories

See Addendum page for models

Have been investigated by UL in accordance with the
Standard(s) indicated on this Certificate.

Standard(s) for Safety:

UL 1863 - Communications-Circuit Accessories .
CSA C22.2 No. 182.4 - Plugs, Receptacles, and
Connectors for Communication Systems.
CSA C22.2 No. 233-09 - Cords and Cord Sets for
Communication Systems

Additional Information:

See the UL Online Certifications Directory at
www.ul.com/database for additional information

Only those products bearing the UL Certification Mark should be considered as being covered by UL's
Certification and Follow-Up Service.

Look for the UL Certification Mark on the product.



Bruce Mahrenholz, Director North American Certification Program

UL LLC

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please
contact a local UL Customer Service Representative at <http://ul.com/aboutul/locations/>



CERTIFICATE OF COMPLIANCE

Certificate Number 20160707-E244889
Report Reference E244889-20110705
Issue Date 2016-JULY-07

This is to certify that representative samples of the product as specified on this certificate were tested according to the current UL requirements.

Modular patch cords: L00000M0081, L00001M0084, L00002M0112, L00003M0055, L00004M0054, L00005M0027, L00006M0033, L00000M0073, L00000M0082, L00001M0085, L00002M0113, L00003M0056, L00000M0075, L00000M0084, L00001M0087, L00002M0115, L00003M0058, L00000M0074, L00000M0083, L00001M0086, L00002M0114, L00003M0057, L00000M0076, L00000M0085, L00001M0088, L00002M0116, L00003M0059, L00003A0049, L00000N0072, L00000N0081, L00001N0084, L00002N0112, L00003N0055, L00004N0054, L00005N0027, L00000A0096, L00001A0097, L00002A0125, L00003A0066, L00000A0230, L00000A0072, L00000A0081, L00001A0090, L00001A0084, L00002A0119, L00002A0112, L00003A0062, L00003A0084, L00003A0148, L00003A0055, L00004A0104, L00004A0093, L00004A0054, L00004A0094, L00005A0067, L00005A0068, L00005A0027, L00006A0187, L00006A0119, L00006A0033, L00006A0108, L00006A0036, L00006A0034, L00006A0057, L00006A0035, L00000A0233, L00000A0075, L00000A0084, L00001A0129, L00001A0206, L00001A0087, L00002A0184, L00002A0115, L00003A0131, L00003A0132, L00003A0058, L00004A0131, L00004A0057, L00004A0152, L00005A0030, L00006A0190, L00006A0045, L00006A0046, L00006A0047, L00006A0194, L00006A0048, L00000A0182, L00000A0183, L00001A0153, L00002A0170, L00003A0116, L00004A0106, L00005A0077, L00006A0123, L00006A0124, L00006A0125, L00000A0231, L00000A0073, L00000A0082, L00001A0168, L00001A0085, L00002A0113, L00003A0101, L00003A0056, L00004A0129, L00004A0055, L00005A0028, L00006A0188, L00006A0037, L00006A0038, L00006A0039, L00006A0040, L00000A0232, L00000A0074, L00000A0452, L00000A0083, L00001A0167, L00001A0086, L00002A0185, L00002A0114, L00003A0133, L00003A0102, L00003A0057, L00004A0130, L00004A0165, L00004A0056, L00004A0119, L00005A0091, L00005A0029, L00006A0189, L00006A0041, L00006A0042, L00006A0043, L00006A0044, L00000A0234, L00000A0076, L00000A0085, L00001A0092, L00001A0088, L00002A0213, L00002A0116, L00003A0184, L00003A0185, L00003A0186, L00003A0059, L00004A0132, L00004A0058, L00005A0031, L00006A0191, L00006A0049, L00006A0050, L00006A0051, L00006A0195, L00006A0052, L00000A0235, L00000A0077, L00000A0086, L00001A0169, L00001A0089, L00002A0117, L00003A0060, L00004A0133, L00004A0060, L00005A0032, L00006A0192, L00006A0053, L00006A0054, L00006A0055, L00006A0056, L00000A0236, L00000A0279, L00000A0130, L00000A0131, L00001A0171, L00001A0123, L00002A0141, L00003A0085, L00004A0071, L00005A0051



Bruce Mahrenholz, Director North American Certification Program
UL LLC

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at <http://ul.com/aboutul/locations/>



CERTIFICATE OF COMPLIANCE

Certificate Number 20160707-E244889
Report Reference E244889-20110705
Issue Date 2016-JULY-07

L00000A0237, L00000A0238, L00000A0226, L00001A0195, L00001A0194,
L00002A0195, L00003A0147, L00004A0134, L00005A0103, L00000A0246,
L00001A0198, L00002A0198, L00003A0150, L00004A0137, L00005A0107,
L00006A0199, L00006A0200, L00006A0201, L00000A0118, L00000A0120,
L00001A0117, L00002A0139, L00003A0078, L00005A0104, L00006A0196,
L00000A0102, L00000A0103, L00001A0099, L00002A0120, L00003A0067,
L00004A0064, L00005A0035, L00000A0189, L00000A0192, L00001A0154,
L00001A0155, L00002A0172, L00002A0173, L00003A0117, L00003A0118,
L00003A0119, L00004A0107, L00004A0108, L00004A0109, L00004A0110,
L00005A0078, L00005A0079, L00005A0080, L00006A0127, L00006A0128,
L00006A0129, L00006A0130, L00006A0131, L00006A0132, L00006A0133,
L00000A0201, L00000A0202, L00001A0161, L00001A0163, L00002A0175,
L00003A0126, L00004A0115, L00005A0085, L00006A0150, L00006A0151,
L00006A0152, L00006A0153, L00000A0197, L00000A0198, L00001A0158,
L00001A0159, L00002A0177, L00003A0124, L00004A0113, L00005A0083,
L00006A0142, L00006A0143, L00006A0144, L00006A0145, L00000A0193,
L00000A0194, L00001A0156, L00006A0155, L00006A0156, L00002A0174,
L00003A0120, L00003A0121, L00004A0111, L00005A0081, L00006A0134,
L00006A0135, L00006A0136, L00006A0137, L00000A0195, L00000A0196,
L00001A0157, L00002A0176, L00003A0122, L00003A0123, L00004A0112,
L00005A0082, L00006A0138, L00006A0139, L00006A0140, L00006A0141,
L00000A0199, L00000A0200, L00001A0162, L00002A0179, L00003A0125,
L00004A0114, L00005A0084, L00006A0146, L00006A0147, L00006A0148,
L00006A0149, L00000A0203, L00000A0204, L00001A0164, L00002A0180,
L00003A0127, L00004A0116, L00005A0086, L00000A0205, L00000A0206,
L00001A0165, L00002A0181, L00003A0128, L00004A0117, L00005A0087,
L00006A0154, L00000A0253, L00000A0254, L00001A0199, L00002A0203,
L00003A0157, L00004A0145, L00005A0113, L00000A0257, L00000A0258,
L00001A0201, L00002A0205, L00003A0159, L00004A0147, L00005A0115,
L00000A0261, L00000A0262, L00001A0203, L00002A0207, L00003A0161,
L00004A0149, L00005A0117, L00000A0265, L00000A0266, L00001A0205,
L00002A0209, L00003A0163



Bruce Mahrenholz, Director North American Certification Program
UL LLC

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at <http://ul.com/aboutul/locations/>



CERTIFICATE OF COMPLIANCE

Certificate Number 20160707-E244889
Report Reference E244889-20110705
Issue Date 2016-JULY-07

L00004A0151, L00005A0119, L00000A0255, L00000A0256, L00001A0200,
L00002A0204, L00003A0158, L00004A0146, L00005A0114, L00000A0259,
L00000A0260, L00001A0202, L00002A0206, L00003A0160, L00004A0148,
L00005A0116, L00000A0263, L00000A0264, L00001A0204, L00002A0208,
L00003A0162, L00004A0150, L00005A0118, L00003A0158, L00002A0225,
L00003A0189, L00003A0195, L00003A0196, L00004A0167, L00003A0202,
L00005A0127, L00006A0309, L00006A0311, L00006A0305, L00004A0170,
L00006A0307, L00006A0313, L00006A0302, L00006A0306, L00004A0171,
L00006A0312, L00006A0310, L00006A0303, L00005A0126, L00006A0308,
L00006A0314, L00006A0304, L00004A0176, L00004A0177, L00005A0128,
L00006A0315, L00006A0316, L00003A0210, L00004A0192, L00005A0140,
L00000M0072, L00000A0329, L00006A0367, L00006A0368, L00006A0369,
L00001A0271, L00006A0394, L00000A0355, L00001A0276, L00000A0356,
L00001A0275, L00002A0269, L00003A0238, L00005A0159, L00000A0338,
L00000A0339, L00001A0261, L00001A0262, L00002A0256, L00002A0257,
L00003A0229, L00004A0205, L00005A0152, L00006A0354, L00006A0356,
L00006A0357, L00000A0340, L00000A0341, L00001A0263, L00001A0264,
L00002A0258, L00002A0259, L00003A0230, L00004A0206, L00005A0153,
L00006A0358, L00006A0359, L00006A0360, L00000A0342, L00000A0343,
L00001A0265, L00001A0266, L00002A0260, L00002A0261, L00003A0231,
L00004A0207, L00005A0154, L00006A0361, L00006A0362, L00006A0363,
L00000A0344, L00000A0345, L00001A0267, L00001A0268, L00002A0262,
L00002A0263, L00003A0232, L00004A0208, L00005A0155, L00006A0364,
L00006A0365, L00006A0366, L00006A0398, L00002A0270, L00005A0164,
L00006A0406, L00006A0397, L00006A0396, L00000A0388, L00000A0374,
L00000A0375, L00001A0286, L00001A0287, L00002A0280, L00002A0281,
L00003A0249, L00004A0224, L00005A0175, L00000A0376, L00000A0377,
L00001A0288, L00001A0289, L00002A0282, L00002A0283, L00003A0250,
L00004A0225, L00005A0176, L00000A0378, L00000A0379, L00001A0290,
L00001A0291, L00002A0284, L00002A0285, L00003A0251, L00004A0226,
L00005A0177, L00000A0380, L00000A0381, L00001A0292, L00001A0293,
L00002A0286, L00002A0287, L00003A0252, L00004A0227, L00005A0178,
L00006A0421, L00006A0422, JT0320F0A6040



Bruce Mahrenholz, Director North American Certification Program
UL LLC

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at <http://ul.com/aboutul/locations/>



CERTIFICATE OF COMPLIANCE

Certificate Number 20160707-E244889
Report Reference E244889-20110705
Issue Date 2016-JULY-07

L00001A0309, L00002A0291, L00006A0424, L00006A0425, L00000A0406,
L80400A0000, L80401A0000, L80402A0000, L80403A0000, L80404A0000,
L80405A0000, L80406A0000, L80406A0001, L80406A0002, L00000A0413,
L80000A0002, L80001A0001, L80003A0001, L80004A0001, L80005A0001,
L80006A0001, L80006A0002, L80000A0000, L80000A0001, L80001A0000,
L80002A0000, L80003A0000, L80004A0000, L80005A0000, L80006A0000,
L80400A0002, L80401A0002, L80403A0002, L80404A0002, L80405A0002,
L80100A0002, L80100A0000, L80100A0001, L80101A0000, L80102A0000,
L80103A0000, L80104A0000, L80105A0000, L80400A0001, L80401A0001,
L80403A0001, L80404A0001, L80405A0001, L00000A0285, L00000A0149,
L00001A0139, L00002A0156, L00003A0098, L00004A0084, L00005A0058,
L00006A0099, L00006A0318, L00006A0319, L00000A0141, L00001A0133,
L00002A0150, L00003A0091, L00004A0090, L00005A0064, L00006A0105,
L83500A0000, L83500A0001, L83501A0000, L83502A0000, L83503A0000,
L83504A0000, L83505A0000, L00000A0422, L00002A0304, L80406A0003,
L80006A0003, L00003A0278, L80003A0003, L80403A0005



Bruce Mahrenholz, Director North American Certification Program
UL LLC

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at <http://ul.com/aboutul/locations/>

